



SBMS Submergence Shield

Use with Greyline PZ32T, PZ32TE or PZ52T Ultrasonic level Sensors to prevent sensor fouling and false readings during accidental submergence.

Instructions

1. Mount with conduit/pipe connection to 3/4" NPT Female coupling.
2. Locate Submergence Shield 0.1 m from sidewall for every 1.0 m depth.
3. Run sensor cable in conduit for mechanical protection.
4. Do not mount in direct sunlight.